


St. MARY'S CHURCH, MALTON (formerly Malton Priory)

North Door, west face


Mortars and condition




Ordinary Portland Cement



Roman Cement



Lime-based mortar



Salt-related decay

