


ST. MARY'S CHURCH OLD MALTON


(FORMERLY MALTON PRIORY)



WEST DOORWAY

CONDITION

PRINCIPAL ZONES OF
SALT-RELATED DECAY
CAUSING BLISTERING
AND DE-LAMINATION



EXTANT SILICATE
COATING APPLIED
1960

